



ADAPTADOR PARA TROCA RÁPIDA

SEM EMBREAGEM DE SEGURANÇA



Modelo	Haste $\varnothing$	Mandril Indicado	D dia.	D1 dia.	D2 dia.	L1	L3	L4	L5
KWES/1B	3.5-11.3	1	30	19	19	17	4	21.5	8
KWES/2B	7.0-18.0	2	48	30	31	30	5	35.0	11
KWES/3B	11-28	3	70	38	48	44	6	55.5	15

Código	Modelo	$\varnothing$	∇	Rosca
03202	KWES/1	7,94	5,95	(1/16 NPT)
03203	KWES/1	11,12	8,34	(1/8 NPT)
03204	KWES/2	14,29	10,7	(1/4 NPT)
03206	KWES/2	17,47	13,09	(1/2 NPT)
03205	KWES/2	17,78	13,49	(3/8 NPT)
03207	KWES/3	23,02	17,25	(3/4 NPT)
06341	KWES/3	28,58	21,41	(1 NPT)