



FRESA DE TOPO PARA CHANFRAR

60° - 90°



Código	d1	a°	l2	l1	z
F MD D 4MM 3C 60° CHANFRAR S/C	4	60°	2	60	3
F MD D 6MM 4C 60° CHANFRAR S/C	6	60°	3	60	4
F MD D 8MM 4C 60° CHANFRAR S/C	8	60°	4	80	4
F MD D 10MM 6C 60° CHANFRAR S/C	10	60°	5	100	6
F MD D 12MM 6C 60° CHANFRAR S/C	12	60°	6	120	6

Código	d1	a°	l2	l1	z
F MD D 4MM 3C 90° CHANFRAR S/C	4	90°	2	60	3
F MD D 6MM 4C 90° CHANFRAR S/C	6	90°	3	60	4
F MD D 8MM 4C 90° CHANFRAR S/C	8	90°	4	80	4
F MD D 10MM 6C 90° CHANFRAR S/C	10	90°	5	100	6
F MD D 12MM 6C 90° CHANFRAR S/C	12	90°	6	120	6